

[:Terry-: Harrison.] North East Durham

Mob:07988445949

Terryterry47@yahoo.com

PERSONAL PROFILE

Good day as mourning is for the dead ;-) one has been an NDT Tech for 15 years

I love to travel and NDT is the job for this exploration of the world and to be paid to do so,

one have worked all over the flat plane [not a globe] and my knowledge will Wake the sheep.

Haha the world is inverted literally we are all slaves

I can do my job with ease and i love to have a laugh when the time is right of course.

ONE IS READY AND ABLE TO START ASAP

QUALIFICATIONS

PCNUTLEVEL 2 -3.1/3.2 nozzle and node

PCN NO: 30-60-49

CCNSG card NO: EC-0807806

VantageCardNO:1541318

Work based training:

2019T.W.I Technology / 10yrs UT Resit and 3.1 3.2 nozzle and node

2015Oceaneering UT 3.8 NDT Inspection.

2017Falk new Tech/Offshore Survival/medical 2017.

2009T.W.I Technology UT 3.1/3.2 NDT Inspection.

WORK EXPERIENCE

MME Group Dintelmond: UT multi skilled Technician 30-8-2023 - 10/2/2024

Main Duties were jobbing about all over Holland, Using UT (shear wave mainly),
inspection for different clients, Butt welds Nozzles, nodes, summarising any problems,
Making reports after inspection with own lap top/ printer, then moving onto next job.
Using Sitiescan 250s and aerosol consumables.

NDT SOUTH WALES UT MP MT 20/6/2020 - 13/8/ 2023

NDT South wales is a company victor ojobo 07436303225 and i have been going down and doing jobs
for his company doing UT tickness and MT PT on sites around south wales.

TECH INSPECTIONS UT / MTtech 06/01/20– 06/04/2020

Jobbing around Britain Inspecting Frameworks Bridges Pipes Welds T's Butts Nozzles Nodes
Using Sonatest D50 and MT 25% to 100% depending on specification.
Logging and reporting Finds.

ADEPT NDT / UT MT Tech 22/07/2019- 16/11/2019

lamb scans on 10 metre 24" pipe work rolled and sent from Italy checking its Integrity...
Using an EPOCH 600 and MT consumables on 20% of the bare material...
Making reports of findings.

OCEANEERING/ UT MT PT Inspector 1/4/2019 - 10/7/2019

Jobbing about different sites inspecting with UT {sonatest D10+}compression plate pipe and T
joints also MT &PT inspection of welds all over the region.

LIEBHERR Cranes / UT NDT tech Sunderland 25/02/2019 - 25/03/2019

MT and UT on butt welds nozzles and nodes using the Krautkramer USM 36. finding any discontinuities and marking up for repair then retesting when the repairs are completed.. reporting findings and logging work.

Alpha / Rope access Tech. Rugby Cemex shutdown 23/01/2019 - 21/02/2019

Rope access drops, netting the vessels. cleaning the inside of the vessels and general maintenance of the plant.

UT technician Holland 29/10/2018 - 21/12/2018

Shear wave of Circ welds of large pipes which are used for foundations.
3.2 Butt weld inspection Using epoch 600 set. Initial UT & MT trade test mandatory.

Sky workers / Rope Access Blasting and Painting Belgium 24/09/2018 - 15/10/2018

NDT on Brackets and Stanchions of the Sugar silo roof using RA. Aid climbing, Rigging, Blasting and Painting.

Safe height solutions / Rope Access. Morden leisure London 12/09/2018 - 20/09/2018

Replacing Brackets to their correct specification using Aid climbing techniques.

CAN & RAC: Rope access Tech. Tottenham hot spur stadium 30/7/2018 - 7/09/2018

Working on the Sky walk platform, Rigging ropes, rope drops, doing which ever job is necessary. Aid climbing under the Sky bridge fixing brackets. Y hanging and finishing cutting out the windows to be fitted. Also supervising steel erectors making sure they are safe.

Safe Height Solutions / Rope Access: Hackney London 01/07/2018 - 14/07/2018

Rope Drops on a new building Painting the parts the other guys cannot reach off the hoists.

NDE:RA CVI inspection and paint repairs 15/05/2018 - 13/06/2018

Rope access CVI inspection of the wind turbine bases in the German wind turbine sector..

Cleaning and repairing the corrosion patches and general inspection of their integrity.

Trac: (Black Pig) Thistle. Rope Access Multi skilled Technician 08/04/2018 - 30/04/2018

CVI and UT thickness checking on the pipe deck floor plates using rope access, Using excel to report and log all the perforations cracked welds and impact damage from above. Assessing the structural integrity of the main stringer beams.

More Jobs history available on request.

References: Available on request

